

# **Heated Indoor Storage Rates**

Storage rates include complimentary trailer storage, exterior power wash, disconnect battery

Boat Type and Length	Storage Rate
Pontoon: 15 – 19 ft	\$745
Pontoon: 20 – 21 ft	\$845
Pontoon: 22 – 30 ft	\$945
Pontoon w/ upper deck	\$1145
V-Hull: 15 – 17 ft	\$745
V-Hull: 18 – 19 ft	\$845
V-Hull: 20 – 21 ft	\$1045
V-Hull: 22 – 24 ft.	\$1065

For all other sizes, call for pricing and availability.

# **Pickup/Delivery Rates**

**Standard Service:** Pickup and delivery at the boat launch with trailer provided, up to 40 miles from Lynden. (Further pickups available upon request.)

**Valet Service:** Pickup and delivery at customer's dock with trailer provided within 40 miles.

24-Hour Trailer Rental	\$75
Standard Service (within 40 miles)	\$199
Standard Service Distance —	\$299
Beyond 40 miles	
Valet Service (available within 40	\$399
miles only)	

# **Other Services**

Hull Wash – Acid	\$20 per linear foot
Interior Detailing	\$20 per linear foot
Fiberglass Buffing	\$20 per linear foot

1016 O'Malley Dr, Coopersville MI 49404 parts@LyndenSportsCenter.com (616) 997-8888

# 2022/2023 Storage and Service Menu

# 2022/2023 Annual Maintenance Service Packages & Rates

Package A: 100-Hour Service — Stabilize fuel, fuel

filters, gear lube, oil & filter change

**Package B:** 300-Hour Service — Package A + impeller, thermostat, belts, power trim & lower unit anodes,

spark plugs

#### **Outboards**

	Package A/ 100-Hr.	Package B/ 300-Hr.
4 – 60 HP	\$260	\$1095
75 – 150 HP	\$299	\$1185
175 – 225 V6 HP	\$325	\$1195
200 – V8 350 HP	\$410	\$1275
All Verados	\$405	\$1480

Inboard/Outboards

Package A	
	i ackage A
4-Cyl	\$365
V6/V8 Small	\$390
V8 Big Block	\$410

# **Winterize Package**

Includes engine drain, fuel stabilizer, antifreeze

Outboards	\$162
Inboard/Outboards	\$260

### Summerize Package (incl. in winter storage)

Includes reconnect battery in spring, run and check engine, check fluid levels and top off if necessary.

Outboards	\$135 + (\$25 per kicker)
Inboard/Outboards	\$165

Battery replacement recommended every 3 years — call for pricing.